

CellAdvisor[™] CA5000 CellAdvisor 5G Release Notes for Version 5.130.003r

Welcome to release 5.130.003r for CA5000 CellAdvisor 5G. This document provides version numbers, a description of new features, and a list of unresolved issues associated with this release, unless otherwise specified.

Contents

Version Numbers	2
What's New in Version 5.130.003r	3
Installation Instructions	3
Fixed Problems	4
Known Limitations	4
Previous Version History	5
Release 5.125.015r	5
Release 5.120.003r	6
Release 5.115.011r	8
Release 5.110.015r	10
Release 5.105.016r	11
Release 5.100.029r	13
Release 5.095.035r	15
Release 5.090.018r	16
Release 5.086.000r	18
Release 5.081.000r	19
Release 5.080.032r	20
Palagea 5 076 002r	22

Release 5.070.021r	23
Release 5.066.001r	26
Release 5.065.041r	27
Release 5.061.002r	28
Release 5.060.067r	29
Release 5.055.025r	31
Release 5.055.021r	32
Release 5.050.022r	33
Release 5.045.032r	35
Release 5.041.001r	36
Release 5.040.028r	37
Release 5.030.049r	38
Release 5.022.009r	40
Release 5.021.003r	41
Release 5.020.029r	42
Release 5.011.008r	43
Release 5.010.031r	44
Release 5.003.007r	45
Release 5.002.007r	46
Release 5.001.022r	47
Technical Assistance	48
Document History	48

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.130.003r
Platform - version	3.5.3

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 /	1103 / 2203 / 3029 / 8160 /	1310 / 2310 / 8352 / 8352 /
	8160 / 7003 / 8160 / 8160 /	8160 / 7003 / 8160 / 8160 /	8352 / 8352
	10001	10001	
CAA06M	Version		
Firmware	6.080.002r	6.080.002r	
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.029.002r		

Recommended Application Software


VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.130.003r

- EMF Performance Enhancement (F001 and F002 only)
 - Measurement time extended up to 24 hours
 - o Auto setup of the PRB region added to 5G NR Traffic Analysis

Installation Instructions

- Visit the linked website below to find the latest firmware and compare it with your version. If your version is older than the latest firmware, download the newest one available. http://celladvisor.updatemyunit.net/
- 2. Unzip the downloaded file and check that there are *.exe file extracted



Upgrade File Name:

- Ca5g_caa-5.XXX.xxxx.xxxxxxxxxx.exe
- 3. Installing upgrade file to USB memory stick and that at least 1 GBytes available, but its maximum capacity not greater than 32 GB for the FAT32 file system.
- 4. Open the downloaded zip file and you will see an exe file that needs to be extracted (not copy and paste) to a USB stick.
- 5. Place a USB stick in PC port.
- 6. Double-click the .exe file, and you will see a new window asking, "Please enter the path for the USB flash drive", and then select your USB stick OK.
- 7. Once the extraction is done, you will see a file folder named 'advisor' on the USB stick.
- 8. Plug in the USB memory stick to the USB Host port on the top side of your CellAdvisor 5G, which is powered via the AC-DC adapter.
- 9. Press the **SYSTEM** Touch key, and then select **Upgrade > USB**.
- 10. Display Upgrade Version, Installed Version and then press the **Start Upgrade** touch key.
- 11. Upgrade screen changes well and the progress bar continues. The upgrade time is 40 minutes to 50 minutes.

At the end of the process the test set will reboot itself to complete the upgrade.

For more information, refer to CellAdvisor 5G User's Guide.

Fixed Problems

- Fixed an error that resulted in incorrect average and current power values in the EMF Scanner mode
- Fixed a bug that displayed the chart format incorrectly in the 5G NR Traffic Analysis mode of EMF Analyzer
- Fixed an issue that did not allow users to access to the root directory of an external storage from a solution application

Known Limitations

None

Previous Version History

This section provides history of previous firmware versions.

Release 5.125.015r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.125.015r
Platform - version	3.5.3

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 /	1103 / 2203 / 3029 / 8160 /	1310 / 2310 / 8352 / 8352 /
	8160 / 7003 / 8160 / 8160 /	8160 / 7003 / 8160 / 8160 /	8352 / 8352
	10001	10001	
CAA06M	Version		
Firmware	6.059.002r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.017.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.125.015r

- Add Auto Reference On/Off and when turned on, auto scaling is done
- Support NET Spectrum Analyzer configuration file
- Add default saving location set to SD card
- EMF Performance Enhancement (F001 and F002 only)
 - o Add altitude and instantaneous values in scanner
 - o Add Channel Number, Channel Step menu on 5G NR Beam/Traffic Analysis
- RA Modules Usability Improvement
 - Add center frequency list in RAN Analyzer
 - Add standalone mode indication in 5G NR Carrier Scanner
 - Set auto trigger to GNSS when the GNSS is locked
 - Save all tabs' results as one report in PDF
- CAA Modules Usability Improvement
 - o Add calibration date & FW version in report
 - Update cable list with JMA cables
 - o Add limit value and band marker display in the measurement screen

Fixed Problems

- Fixed an issue that the NR bandwidth, 15 and 20 MHz are missing in the auto configuration menu in EMF
 5G NR Traffic Analysis
- Fixed an incorrect measurement screen display when moving maker power value and marker in EMF
 Spectrum
- Fixed an issue that integration BW for span is incorrectly displayed in EMP Spectrum
- Fixed an issue that sweep is halted when changing frequency in the case of RBW manual in Sweep Tuned
 Spectrum
- Fixed an issue that 'Overwrite' is not displayed when selecting file type as multi
- Fixed an issue that marker table is not fully displayed in the result when saving report
- Fixed an issue 20 MHz (8 AxC) bandwidth option is missing in RFoCPRI Interference Analyzer

Known Limitations

None

Release 5.120.003r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.120.003r
Platform - version	3.5.3

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 / 8160 / 7003 / 8160 / 8160 / 10001	1103 / 2203 / 3029 / 8160 / 8160 / 7003 / 8160 / 8160 / 10001	1310 / 2310 / 8352 / 8352 / 8352 / 8352
CAA06M	Version		
Firmware	6.058.001r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.016.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.120.003r

- EMF Performance Enhancement (F001 and F002 only)
 - Added 5G NR Traffic Analysis
- RA Modules Usability Improvement
 - o Redefine for screen capture.
 - o Show measured BW in spectrum view of Interference Finder
 - o Display the DL and UL channel number of the interference Analysis.
 - o RF Source controls is available on Interference Analyzer, on TAGS
 - o Add P/s-SS PWR To OTA Channel Scanner for LTE/NR/NSA
 - o Center Frequency list support to TDD Auto Gated Spectrum
 - o Bias Voltage Menus in RA Application
 - o IA/RtSA/RFoCPRI logging at multi traces.
 - o new P/F limit on Cellphase Sync and new reference for Time Error
 - Add Recode and Replay in TDD Auto Gated Spectrum

- CAA Modules Usability Improvement
 - Enable Save & Screen Capture During Trace Load in CAA
 - Saving All Tabs' Results as One Report
 - Limit Line Disappears after Mode Change
 - o Calibration on 2 port Transmission
 - o Display of CAA Model & Serial Number
- Supporting Traditional Chinese GUI

- Fixed an issue that some frequency bands are missing from the detected carrier in Blind Scanner
- Fixed an issue that the result of save CSV file is incorrect in 5G NR Signal Analyzer Channel Scanner
- Fixed an issue that the Align button is not working when selecting NEM as Samsung in RFoCPRI Interference Analyzer
- Fixed an issue that the result of save CSV format is incorrect (missing title/typo/incorrect unit) in LTE
 Signal Analyzer
- Fixed an issue that the frequency count function is not operating properly

Known Limitations

None

Release 5.115.011r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.115.011r
Platform - version	3.5.2

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0

DSP Module	1103 / 2203 / 3029 / 8160 /	1103 / 2203 / 3029 / 8160 /	1310 / 2310 / 8352 / 8352 /
	8160 / 7003 / 8160 / 8160 /	8160 / 7003 / 8160 / 8160 /	8352 / 8352
	10001	10001	
CAA06M	Version		
Firmware	6.057.001r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.015.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.115.011r

- RA Modules Usability Improvement
 - Enhancement of SIB1 decoding for TAGS / PLMN / 5GNR SA and NSA network identification
 - Measurement selection on Freq/Time/Power variation
 - Add a carrier name in NSA Analyzer
 - Add a function for saving a result as CSV in Blind Scanner
 - o Remove the automatic timestamp regardless of file types (multi or single)
 - o Improve RFoCPRI sweep speed
- Improvement of OneCheck
 - Add key parameters for multiple selections
 - Add to Favorite
 - Add a function for uploading a pdf file and a Youtube video as Instruction files.
- Usability improvement for EMF Analyzer
 - Add limit line to EMF NR bar chart.
 - Add a function for saving result as CSV, logging as CSV in EMF Scanner
 - o Add a unit of % in Amp/Scale for EMF Scanner

Fixed Problems

- Fixed an issue that incorrect DTF measurement in unit setting to foot
- Fixed an issue that uploading the saved image file is not successful and marker menu is disabled
- Fixed an issue that displays an incorrect Max Hold value after selecting Set Write/Min/Max
- Fixed an issue that the result of logging as CSV is not correctly saved in Route Map of Channel Scanner
- Fixed an issue that Atten and Preamp are not changed in Route Map of Channel Scanner

Known Limitations

None

Release 5.110.015r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.110.015r
Platform - version	3.5.2

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 / 8160 / 7003 / 8160 / 8160 / 10001	1103 / 2203 / 3029 / 8160 / 8160 / 7003 / 8160 / 8160 / 10001	1310 / 2310 / 8352 / 8352 / 8352 / 8352
CAA06M	Version		
Firmware	6.056.001r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.014.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.110.015r

- Supportability of RAN Analyzer (CA5000-S046)
- RA Modules Usability Improvement

- Add 5G NR PCI Dominance
- o Support Online Interference Analysis
- o Add Limit for time error on 5GNR, LTE, DSS Freq/Time/Power Variation Analysis
- Add 5G NR Map Allocation Utilization with Channel Power
- Supportability of Workflow Automation
- Supportability of CAA Standalone Mode for Cable Delay Measurements
- Improvement of Usability
 - o Improve Auto RFoCPRI Detection
 - CAA Usability
 - Display of number of items and selected items in File Manager view
 - Warning Pop-up when saving a Result/Report when performing Cal Off
 - Pass/Fail On/Off toggle menu in Limit Line Setting
 - Measurement Hold working after Save Then Stop in CAA

- Fixed an issue that no CAA display at Tests menu in Home tab after creating CAA favorites
- Fixed an issue that CAA Check prompt is running abnormally
- Fixed an issue that SSB Auto search does not work for 5GNR Freq/Time/Power Variation

Known Limitations

None

Release 5.105.016r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.105.016r
Platform - version	3.5.1

Hardware Configuration

	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 /	1103 / 2203 / 3029 / 8160 /	, , , , , , ,
	8160 / 7003 / 8160 / 8160 /	8160 / 7003 / 8160 / 8160 /	8352 / 8352
	10001	10001	
CAA	Version		
Firmware	6.055.001r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.013.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.105.016r

- Supportability of Online Route Map (CA5000-S014N)
- TDD Auto Gated Spectrum Enhancement
 - o Supportability of LTE-TDD
 - Improve sensitivity by supporting lower RBW
- LTE Performance Enhancement
 - Decode LTE signal without PSS and SSS
 - LTE PDSCH prerecording without CCD
- Scanner
 - Added Route Map
- Improvement of Usability
 - o Independent detector per trace
 - Each trace (T1-T6) can be set trace type (W,m,M,c) and detector type (Normal, RMS, Peak, Sample, Negative Peak) individually and independently.
 - o Auto attenuation setting in Channel Scanner
 - o Add auto preamp off feature in Real-Time Spectrum Analyzer
 - Change the default value of RFoCPRI vertical scale to 5dB
 - Add PDF Report Generator feature that shows setup information when capturing the screen in SA (Spurious Emissions), LTE (Spurious Emissions and Carrier Aggregation), 5G
 NR (Spurious Emissions and Carrier Scanner), NSA (NSA Scanner), DSS (Spurious Emissions, Subframe, and Frame), and 5G TM (Transmitter Spurious Emissions)
 - o Decoding MIMO info in LTE MIB and configure it automatically

o Port selection improvement in GUI (F030 and F044 only)

Fixed Problems

- Fixed an issue that the port selection button (F030 and F044 only) is missing after upgrade.
- Fixed an issue that LTE menu selection is missing in Gated Sweep measurement.
- Fixed an issue on noise marker in Spectrum Analyzer keep noise marker for delta, delta pair and enable delta maker function in Field Strength.
- Fixed the maximum number of files to be saved or moved in Folder up to 4300 and an alert message will display in case it exceeds the limit number (4300).
- Fixed an issue that Save on Event does not work for selecting only one file and holding the measurement when occurring event.

Known Limitations

None

Release 5.100.029r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.100.029r
Platform - version	3.5.0

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8160 /	1103 / 2203 / 3029 / 8160 /	1310 / 2309 / 8352 / 8352 /
	8160 / 7003 / 8160 / 8160 /	8160 / 7003 / 8160 / 8160 /	8352 / 8352
	10001	10001	
CAA	Version		
Firmware	6.054.001r		

RF Module	1.0
DSP Module	6001 / 2021/09/16
RFPM	Version

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.100.029r

- Supportability of TDD Auto Gated Spectrum (CA5000-S021)
- Supportability of Cell Phase Synchronization (CA5000-S045)
- 5GTM Performance Enhancement
 - MIMO in one port
- EMF Performance Enhancement
 - o Limit on Scanner
 - System scaling factor
 - Extrapolation
- RFoCPRI Interference Analyzer Enhancement
 - Auto CPRI Configuration
 - Supports latest Nokia format and Legacy Ericsson format
 - Supports one button report generation for interference/PIM.
- Improvement of Usability
 - Auto file naming for Radio Analysis
 - Auto trace clear Write / Max / Min
 - Center frequency list
 - o Time error measurement offset
 - Setup file compatibility across the platforms
 - Adopt CAA file explorer
- Other Enhancement
 - o Operation in low center frequency of RtSA and LTE

Fixed Problems

- Fixed an issue that does not setup load when there is a space
- Fixed an issue the RF Power Meter displays 100 dBm (1 Megawatt) power reading with JD731B.
- Fixed an issue that displays no parameter setup menus for RF Source in the full Measure Setup screen.

Known Limitations

None

Release 5.095.035r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.095.035r
Platform - version	3.4.0

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 8158 /	1103 / 2203 / 3029 / 8158 /	1310 / 2309 / 8351 / 8351 /
	8158 / 7003 / 8158 / 8158 /	8158 / 7003 / 8158 / 8158 /	8351 / 8351
	10001	10001	
CAA	Version		
Firmware	6.053.001r		
RF Module	1.0		
DSP Module	6001 / 2021/09/16		
RFPM	Version		
Firmware	7.011.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.095.035r

- Supportability of Blind Scanner FR2 in F002 or F002-O
- Supportability of EMF Analyzer FR2 in F002 or F002-O
- Supportability of Auto File Naming

- Cable and Antenna Analyzer
- RFoCPRI Interference Analyzer Enhancement
 - Auto CPRI Configuration lets you set link rate, antenna and carrier search for Port 1 or Port 2 automatically
- Supportability of BDA800 Antenna Handle with following capability:
 - Interference Finder
 - Radar Chart
 - Persistent Interference Finder
 - Persistent Radar Chart
- Supportability of TM Signal Analyzer for 3GPP Release 15 and 16

- Fixed a time conversion error in DTF when units change from meter to feet
- Fixed an issue that time error does not change based on distance setting in 5G NR Carrier
 Scanner
- Fixed an issue that searched SSB Frequency in Blind Scanner is not properly applied in SSB Frequency for NR
- Fixed an issue that reference level is not changed properly in LTE OTA ID Scanner
- Fixed an issue that saving feature does not work after about 20 minutes of operation in
 Spectrum Route Map

Known Limitations

None

Release 5.090.018r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.090.018r
Platform - version	3.3.0

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 4145 /	1103 / 2203 / 3029 / 4145 /	1309 / 2309 / 8349 / 8349 /
	5145 / 7003 / 8145 / 9134 /	5145 / 7003 / 8145 / 9134 /	8349 / 9336
	10001	10001	
CAA	Version		
Firmware	6.052.001r		
RF Module	1.0		
DSP Module	6001 / 2020/10/20		
RFPM	Version		
Firmware	7.010.001r		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.090.018r

- Supportability of EMF Analyzers with the following capability:
 - Spectrum
 - Scanner
 - o 5GNR Beam Analysis
- Supportability of Blind Scanner
- LTE Performance Enhancement
 - o Improved Dynamic range at Multi PCIs
- Supportability of Custom Favorite
- RFoCRI Interference Analyzer Enhancement
 - o Adding Ericsson RFoCPRI 9/1 mapping
 - Enhancing Spectrum Speed and GUI
- RF Power Meter
 - Moving Internal RF Power Meter to the Utility of Spectrum Analyzer
 - Supporting External RF Power Meter when connected 730 series RF Power sensor using an USB cable

Fixed Problems

 Fixed an error that brings wrong value when selecting a Plot Item as Peak in Route Map of Spectrum Analyzer

- Fixed an error that alerts a pop-up asking to configure the corresponding channel band even though correct channel band was already defined
- Fixed an error that displays -999 in EMV value when the signal is not received: The negative value is not applied for average calculation and not displayed
- Fixed multi-tab setup file recall issue
- Fixed an error that incorrect audio sound decode in AM/FM Sound Demodulation
- Fixed an issue in CAA that causes the trace disappeared after performing a calibration with an EZ-Cal kit when the system language is in German.

Known Limitations

None

Release 5.086.000r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.086.000r (19/07/2021)
Platform - version	3.2.1-r0. (04/05/2021)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1103 / 2203 / 3029 / 4144 /	1103 / 2203 / 3029 / 4144 /	1307 / 2309 / 8349 / 8349 /
	5144 / 7001 / 8144 / 9134	5144 / 7001 / 8144 / 9134	8349 / 9336
CAA	Version		
Firmware	6.051.001r		
RF Module	1.0		
DSP Module	6001 / 2020/10/20		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.086.000r

- Fast Gated Sweep
 - o Improved sweep speed
- NR Performance Enhancement
 - o Improved Dynamic range at Multi PCI

Fixed Problems

- Fixed a bug in the CAA that causes the limit line on the bottom or right window missed from loading in the dual display mode
- Fixed a bug in RFoCPRI quad spectrum view that causes four charts display the same spectrum due to wrong RX map positioning setup

Known Limitations

None

Release 5.081.000r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.081.000r (18/05/2021)
Platform - version	3.2.1-r0. (04/05/2021)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
DSP Module	1101 / 2203 / 3029 / 4144 /	1101 / 2203 / 3029 / 4144 /	1305 / 2309 / 8347 / 8347 /
	5144 / 7001 / 8144 / 9134	5144 / 7001 / 8144 / 9134	8347 / 9336
CAA	Version		
Firmware	6.050.002r		
RF Module	1.0		
DSP Module	6001 / 2020/10/20		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.081.000r

None

Fixed Problems

Fixed an error that SSB frequency has a difference of 1 KHz when executing GSCN search

Known Limitations

None

Release 5.080.032r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.080.032r (10/05/2021)
Platform - version	3.2.1-r0. (04/05/2021)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	F030 / F044
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	2.0 / 3.0 / 3.0
DSP Module	1101 / 2203 / 3029 / 4144 /	1101 / 2203 / 3029 / 4144 /	1305 / 2309 / 8347 / 8347 /
	5144 / 7001 / 8144 / 9134	5144 / 7001 / 8144 / 9134	8347 / 9336
CAA	Version		
Firmware	6.050.002r		
RF Module	1.0		
DSP Module	6001 / 2020/10/20		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.080.032r

- Frequency Expansion
 - o Added Frequency Option up to 30 GHz and 44 GHz with two RF ports
- NR Performance Enhancement
 - Improved algorithm for SSB search
- Other Enhancement
 - Added Auto Preamp feature in 5GNR Analyzer, NSA Analyzer, LTE OTA Analysis, DSS OTA Analysis
 - o Added Dual gated sweep

Fixed Problems

- Fixed an error that displays wrong sync indication in 5G NR Beam Analyzer and Route Map
- Fixed an error that decodes the wrong LTE Antenna port
- Fixed an error that CDM JSON file is not created when there is space in the file name to be saved
- Fixed an error that CAL status changes when loading a trace result saved after an EZ-Cal Calibration
- Fixed an error that sets the inappropriate attenuation value and result display when auto scale function is executed in Gated Sweep mode
- Adjusted S-SS SINR's max range scale to 20 in 5G NR Route Map
- Fixed an error that Replayer does not display information for the saved data and time when logging in Interference Analyzer, Real-time Spectrum Analyzer, and CPRI Analyzer

Known Limitations

None

Release 5.076.002r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.076.002r (11/03/2021)
Platform - version	3.0.2-39f413a. (10/02/2021)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	
DSP Module	1098 / 2203 / 3029 / 4143 / 5143	1098 / 2203 / 3029 / 4143 / 5143	
	7001 / 8143 / 9134	7001 / 8143 / 9134	
CAA	Version		
Firmware	6.030.001r	6.030.001r	
RF Module	1.0		
DSP Module	6001 / 2020/10/20		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.076.002r

- Frequency / Time / Power Variation Enhancement
 - Improved to change units (nsec/usec) corresponding to scale based on the measurement result
 - o Adjusted the trigger information menu location in the Top Information
 - Forced the strongest PCI setting and changed the PCI status to Manual at the measurement

- GUI Enhancement
 - CAA
 - Changed the Mode and Measure icon in the title bar and the Hold icon in the side bar
 - DSS OTA Channel Scanner
 - Added new menus for SSB Auto/Manual Search and PCI Auto/Manual setting
- DSS Performance Enhancement
 - OTA ID Scanner
 - Improved algorithm for power measurement
- Other Enhancement
 - Added Auto Preamp feature in Sweep tuned Spectrum Analyzer, Real-time Spectrum Analyzer, and Interference Analyzer
 - Added a display selection option to plot results in different displays for the LTE chart in NSA Analyzer
 - o Added additional LTE-FDD new bands 73, 74, 85, 87, and 88 to the channel standard list
 - Added distance menu setting by each multi carrier in Configuration of Carrier Scanner in
 5G NR Signal Analyzer
 - o Added a reference level menu to DSS OTA ID Scanner

- Fixed an issue that displays the SSB unlock and no SSB detected message when a logged file is loaded in the NR route map measurement
- Fixed a problem that causes the Wi-Fi and Bluetooth option activation issue
- Fixed an issue that a pop-up message and a menu to be selected are overlaid in Full Menu screen

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.070.021r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.070.021r (16/11/2020)
Platform - version	3.0.1-f33895a. (12/11/2020)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	
DSP Module	1098 / 2203 / 3029 / 4143 / 5143	1098 / 2203 / 3029 / 4143 / 5143	
CPRI Module	7001 / 8143 / 9134	7001 / 8143 / 9134	
CAA	Version	Version	
Firmware	6.030.001r		
RF Module	1.0		
DSP Module	6001 / 2019/05/11		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.070.021r

- Supportability of 5G NR PDSCH Analyzers with the following capability:
 - PDSCH Constellation
 - o EVM vs Subcarrier
 - Allocation Mapper
- 5G NR Enhancement
 - New Decoding
 - Added channel PBCH-DMRS, S-SS RSSI in 5GNR Beam Analyzer, Beam Availability Index, Carrier Scanner
 - Added channel PBCH-DMRS, S-SS RSSI in NSA and DSS OTA ID Scanner
 - Added Multi PCIs decoding
 - New capability
 - Added Multipath Profile
 - Added new indicators for No-SSB detection (Sync) and removed a warming message when the SSB is not detected
 - Added Time offset for beam index in Mulit-PCIs
 - Added a feature to enter SSB frequency with GSCN number

- Added a feature to sort beam measurement result in Beam Analyzer with RSRP and PCI
- Added a feature to distinguish different PCIs clearly
- Added P vs T Frame Mask
- LTE Enhancement
 - Added Auto Preamp function in LTE
- Other Enhancement
 - Added Freg/Time Offset variation at multi carriers
 - Added a feature to untie the GOMV file from the MCFV file to zoom in farther as needed
 - Added Beam Display up to 64 on the screen
 - o Added EIRP1, EIRP2, SUM, and MAX values in NR Channel Power
 - Added a pop-up window to show all channels if LTE/NR channel is selected in two different frequency range with the same center frequency
 - o Added a feature to load a result file with data with map or data only in Route Map
- Supportability of Job Manager
- Unit change from ppm and usec to ppb and ns in Freq/Time/Power Variation (In the case of unit change in thousands, it is to be displayed in ppm and usec)

- Fixed an issue that the imported cellsite in Route Map does not move when zooming the map
- Fixed an issue that the color codes do not match with changed Plot Item in Route Map
- Fixed an issue that the activation of the Gated Sweep option does not properly work in Global
 30 Days License
- Fixed an issue that the x- and y-coordinates are seen (0,0) in the result csv file for Indoor Map
- Fixed an issue that some SCPI commands are not working and missing
- Fixed an issue that unmatching color codes are displayed when gomv file is loaded
- Fixed an issue that the saved result csv file shows incorrect measurement data in DSS Signal Analyzer
- Fixed an issue that CA5G is unable to get stable measurements in a location with good reception in Time Alignment Error in DSS Signal Analyzer
- Fixed an issue that USB Flash is not recognized in the following menu, System -> video player -> file open

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.066.001r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.066.001r (30/07/2020)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1097 / 2202 / 3029 / 4033 / 5014	1097 / 2202 / 3029 / 4033 / 5014
CPRI Module	7001 / 8143 / 9134	7001 / 8143 / 9134
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.066.001r

o None

Fixed Problems

Fixed an issue regarding unable to connect to StrataSync

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version. • If you encounter an error when connecting to the StrataSync server, please install the latest recovery file. (Note that running the recovery file erases all the saved user files in the internal memory. Please make sure to back up all the saved user files in advance)

Release 5.065.041r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.065.041r (23/07/2020)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1097 / 2202 / 3029 / 4033 / 5014	1097 / 2202 / 3029 / 4033 / 5014
CPRI Module	7001 / 8143 / 9134	7001 / 8143 / 9134
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.065.041r

- Added DSS signal analysis option
- Added NSA signal analysis option
- o Improved Probability of Intercept (POI) spec in Real-Time Spectrum Analyzer
- Supported InterferenceAdvisor
- Added logging capability for NR carrier scanner and LTE (FDD/TDD) channel scanner result as csv format

- Fixed an issue regarding unable to change Start/Stop Frequency between FR1 and FR2
- Fixed an issue regarding unable to work Preamp for RSRP
- Fixed an issue regarding recognition error for effective beam in NR
- Fixed an issue regarding Gated Sweep trigger drift @ no GPS locking
- Fixed an issue regarding unable to change the Integrated BW in the Channel Power of RF Analysis mode
- Fixed an issue regarding unable to search SSB automatically with proper pre-amp status

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.061.002r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.061.002r (18/05/2020)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1095 / 2140 / 3029 / 4033 / 5014	1095 / 2140 / 3029 / 4033 / 5014
CPRI Module	7001 / 8133 / 9134	7001 / 8133 / 9134
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.061.002r

None

Fixed Problems

- Fixed an issue regarding not showing selected manual PCI information when selecting PCI
 Mode to Manual and Sweep Speed to Fast in 5G NR Route Map
- Fixed an issue regarding unable to change PCI Mode to Manual in 5G NR Carrier Scanner
- Fixed an issue regarding unable to set frequency extension for F002N and F002NO
- Fixed an issue regarding unable to perform RF calibration when executing a self-test

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.060.067r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.060.067r (06/05/2020)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1095 / 2140 / 3029 / 4033 / 5014	1095 / 2140 / 3029 / 4033 / 5014
CPRI Module	7001 / 8133 / 9134	7001 / 8133 / 9134
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.060.067r

- Supportability of 5G TM Signal Analyzer with the following capability:
 - o BS Output Power
 - Occupied Bandwidth
 - o ACLR
 - o Multi-ACLR
 - Operation Band Unwanted Emissions
 - Transmitter Spurious Emissions
 - Transmit ON/OFF Power
 - Modulation Quality
 - o MIMO Time Alignment Error
 - o CA Time Alignment Error
- 5G NR Enhancement
 - Added SSB Auto Search mode (Auto / Manual)
 - IQ logging capability in some measurements
 - Added Logging as CSV in Carrier Scanner
- LTE Enhancement
 - IQ logging capability in all measurements except Multi-ACLR and Spurious Emissions
 - Added PCI manual setup to support LTE OTA PCI forcing
 - o Added Logging as CSV in Channer Scanner
- Graph plot and ability to save time offset and frequency error in NR and LTE in a log file
- Support Chinese language
- Added a pop-up message after logging to save the result. When you tap Yes, it directs you to save a file type as Result and Result to CSV as a default in Route Map
- Added Sweep Once feature in top panel

Fixed Problems

- Fixed an issue regarding unable to switch Preamp to on when changing mode after using Preamp on in Real-time Spectrum Analyzer
- Fixed an issue regarding reverse limit Pass or Fail judgement in CAA one port cable
- Fixed an issue regarding unable to input a specific frequency, SCS, and SSB frequency in 5G NR Carrier Scanner
- Fixed an issue regarding wrong Preamp 1 and 2 status (gray-out) when changing to DNC frequency range

- Fixed an issue regarding logging file compatibility in old Real-time Spectrum Analyzer and Interference Analyzer
- Fixed an issue regarding unable to do PCI forcing when manually setting PCI in LTE OTA Control Channel

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.055.025r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.055.025r (19/12/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1095 / 2140 / 3029 / 4033 / 5014	1095 / 2140 / 3029 / 4033 / 5014
CPRI Module	7001	7001
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.055.025r

Added Beeper On/Off function in System Settings menu when IF overloaded.

Improved Spectrum Noise Level in RFoCPRI mode.

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.055.021r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.055.021r-1 (13/12/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	
DSP Module	1095 / 2140 / 3029 / 4033 / 5014	1095 / 2140 / 3029 / 4033 / 5014	
CPRI Module	7001	7001	
CAA	Version	Version	
RF Module	1.0		
DSP Module	6001 / 2019/05/11		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.055.021r

- Added new hardware frequency options (F018 and F018-0) up to 18.5 GHz.
- 5G NR Enhancements

- Improved NR beam decoding algorithm
- Improved SINR measurement result with a new algorithm
- o Added PS-SNR into 5GNR OTA Beam analyzer and Carrier Scanner
- o Added Beam Availability Index into NR OTA analysis measurement
- Added EIRP (Equivalent Isotropically Radiated Power) into NR Channel Power measurement
- Added PS-SNR into LTE OTA ID Scanner measurement
- RtSA POI enhancement from 100 usec to 34 usec.

- Usability enhancement by improved Calculated PIM operation method and the interwork of frequency & span in PIM Detection menu.
- Added SCPI commands for frequency Error & Time Error of NR Carrier Scanner

Known Limitations

Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.050.022r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.050.022r-1 (04/11/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1089 / 2134 / 3029 / 4033 / 5014	1089 / 2134 / 3029 / 4033 / 5014
CPRI Module	7001	7001
CAA	Version	

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.050.022r

- 5G NR Enhancements
 - o 5G NR measurements (beam analyzer, Carrier scanner and Route map).
 - Auto pre-amp and attenuation
 - SSB Auto search for OTA analysis measurement
 - Added Fast and Normal mode for measurement speed
 - Improved power plotting measurement & PCI plot (20 different PCI colors)
 method in route map
 - Multi PCI display in fast mode for OTA analysis measurement
 - Added sweep tuned RF measurement capabilities into 5G NR Trigger Spectrum mode.
- Improvements in RFoCPRI Spectrum
 - Added Multi Active Trace
 - Added PRB Table
- Upgrade path recommendation
- Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Fixed Problems

- Fixed the error of logging file replay in Real time spectrum menu.
- Fixed the problem of no moving or too slow moving of marker when amplitude changed in CAA
 mode
- Fixed the problem of trace overlay and UI display when upload the saved file by 'Trace Type -> Load' in CAA mode.

Known Limitations

 Need to upgrade to 5.030 first for 5.021 or earlier released firmware versions before an upgrade to the latest firmware version.

Release 5.045.032r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.045.032r-1 (30/09/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version	
	F001	F002
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0
DSP Module	1089 / 2134 / 3024 / 4025 / 5010	1089 / 2134 / 3024 / 4025 / 5010
CPRI Module	7001	7001
CAA	Version	
RF Module	1.0	
DSP Module	6001 / 2019/05/11	

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

Page 35 of 50

What's New in Version 5.045.032r

- CA5G supports RFoCPRI interference Analysis up to 10.1G link rate
 - o Enhanced IQ Data Block Viewer
 - Enhanced Rx Settings
 - o RFoCPRI Spectrum
 - o RFoCPRI Spectrogram
 - o RFoCPRI PRB Table
 - o RFoCPRI Alarm Sound indicator
 - Spectrum logging and Replay
 - Support Setup and Favorite

- Improved flatness of RTSA noise floor in panorama view
- Added the option of logging as CSV in LTE Channel scanner & ID scanner
- Changed the default setting of limit lines of SS-RSRP & SS-SINR in beam analyzer from On to Off

Known Limitations

None

Release 5.041.001r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.041.001r-1 (27/08/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	
DSP Module	1089 / 2134 / 3024 / 4025 / 5010	1089 / 2134 / 3024 / 4025 / 5010	
CAA	Version		
RF Module	1.0		
DSP Module	6001 / 2019/05/11		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.041.001r

None

- CA5G Unit freezes sometimes when playing around with the FO (Fiber Optics) application.
- When CA5G turns on, CA5G focuses the CellAdvisor 5G application regardless of external module attachment condition.

Known Limitations

None

Release 5.040.028r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Installed Software

VIAVI Software	Version
Celladvisor5G-solution	5.040.028r-1 (16/08/2019)
Platform - version	2.0.17-ef8c056 (13/08/2019)

Hardware Configuration

CellAdvisor 5G	Version		
	F001	F002	
RF Module	1.0 / 2.0 / 4.0	1.0 / 2.0 / 1.0	
DSP Module	1089 / 2134 / 3024 / 4025 / 5010	1089 / 2134 / 3024 / 4025 / 5010	
CAA	Version	Version	
RF Module	1.0	1.0	
DSP Module	6001 / 2019/05/11		

Recommended Application Software

VIAVI Software	Version
JDMapCreator	1.8 and after

What's New in Version 5.040.028r

- Supportability of Cable Antenna Analyzer with the following capability:
 - o Reflection VSWR and Return Loss

- DTF VSWR and Return Loss
- 1 Port Cable Loss
- o 1 Port Phase
- o 2 Port Transmission
- Smith Chart
- o RF Source
- Supportability of Optical Time Domain Reflectometer with the following module:
 - o E4106MA2 APC, PC
 - E4126MA2 APC, PC
 - o E4126MA3 APC, PC
 - o E4136MA2 APC, PC
 - E4136MA3 APC, PC
 - o E4146QUAD
- Capability of RF CW source only when connected with a CAA module
- Enhancement of Gated Sweep with 5G NR signal support

- With the modified Antenna detection and Peak Antenna indication functions in LTE menu, you can measure according to the manual setting of Antenna port (1, 2, 3, 4 not Auto).
- Improved to be possible to measure when you set Auto mode in LTE Test Model 3.x (QPSK and 16 QAM mixed) signals supplied, i.e., PDSCH Modulation type set to Auto.

Known Limitations

- For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.
- Downgrade is only supported through re-image. (Platform version 2.0.x --> 1.0.x)

Release 5.030.049r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.030.049r		
	F001	F002	
RF Module	1.0 / 2.0	1.0 / 2.0 / 1.0	
DSP Module	1089 / 2134 / 3024 / 4025 / 5010	1089 / 2134 / 3024 / 4025 / 5010	

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.030.049r
JDMapCreator	1.8 and after

What's New in Version 5.030.049r

- Supportability of LTE FDD TDD Analyzer
 - Capability of LTE FDD TDD RF Analysis
 - Capability of LTE FDD TDD Modulation
 - o Capability of LTE FDD TDD OTA

Fixed Problems

- Fixed SSB detection failed message pop-up after SSB detection in normal condition in 5GNR
 Spectrum Emission Mask.
- Improved the way to adjust the reference level: by sliding a finger on the screen, reference level can be adjusted in 5GNR beam Analyzer, carrier scanner, Power vs Time.
- Channel step boundary range of 5GNR Signal Analyzer broadened from 100 to 10000.
- Multi-ACLR frequency range support up to 24 40 GHz in 5GNR Analyzer.
 - o Previous: 9 kHz 6 GHz
 - O Current version: 9 kHz 6 GHz, 24 40 GHz

Known Limitations

• For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.

Release 5.022.009r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.022.009r	
	F001	F002
RF Module	1.0 / 2.0	1.0 / 2.0 / 1.0
DSP Module	1089 / 2134 / 3024 / 4022	1089 / 2134 / 3024 / 4022

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.022.009r
JDMapCreator	1.8 and after

What's New in Version 5.022.009r

NA

Fixed Problems

- Route Map menu In case of In-door map file, deleted x, y coordinates. Latitude, longitude display replaced by x, y coordinates in CSV Result file.
- Fixed Wi-Fi connection issue.
- Fixed the screen display problem of noise level and signal in frequency change.
- Fixed AA Handle Azimuth accuracy issue: Resolved Azimuth value display problem in measurement after AA Handle connected to CA5G and initialization.

Known Limitations

• For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.

Release 5.021.003r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.021.003r	
	F001	F002
RF Module	1.0 / 2.0	1.0 / 2.0 / 1.0
DSP Module	1088 / 2133 / 3024 / 4022	1088 / 2133 / 3024 / 4022

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.021.003r
JDMapCreator	1.8 and after

What's New in Version 5.021.003r

NA

Fixed Problems

- Resolved current GPS position update issue when zoom into the Map in Route Map menu.
- Fixed Route Map display error by GPS number of digits in Route Map in 5.020.029r release.
- Fixed color display error for 5GNR P vs T (Symbol) Slot format DL/UL in some format part.

Known Limitations

• For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.

Release 5.020.029r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.020.029r	
	F001	F002
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0
DSP Module	1088 / 2133 / 3024 / 4022	1088 / 2133 / 3024 / 4022

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.020.029r
JDMapCreator	1.8 and after

What's New in Version 5.020.029r

- Supports Auto Select in Clock Source.
- Added Confirm button (play and stop button) and Undo function(only available when Plot Point switches to Position) at Route Map menu.
- Added Cellsite icon with Azimuth & it is activated when Cellsite information is imported at Route Map menu.
- Enhancement of 5G NR Signal Analyzer
 - Automatic calculation of the SCS offset
 - SSB GSCN Auto: New method to search 5G beams (SSB block) center frequency according to 3GPP global synchronization channel number (GSCN)
 - SSB Full Auto: New method to search 5G beams (SSB block) frequency down to sub-carrier spacing, e.g. 120KHz or 240KHz
 - Beam Power Accuracy: reference signal received power (RSRP) and signal to interference noise ratio (SINR) with revised calculated values
 - o Added Triggered Spectrum Menu in 5GNR ACLR
 - o P vs T symbol time span expansion
 - P vs T symbol UL/DL indicated by different colors
 - At Route Map menu, added SS-SINR, SS-RSRQ measurement items under Map conf / Plot Item

- Resolved the issue to import sizeable maps on Route Map and the ability to set a single layer map
- Resolved the bug issue 'No GPS or No RSRP value in 5GNR Signal Analyzer & Route Map' for all regional settings.
- The 1st carrier center frequency set in 5GNR Carrier Scanner is now maintained in other modes.
- Fixed X,Y coordinate indication error for Position at Indoor Map in Route Map menu.
- Fixed Spectral Density calculation error in 5GNR Channel Power.
- Fixed the error of no GPS Point indication at single map file in Route Map menu

Known Limitations

• For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.

Release 5.011.008r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.011.008r	
	F001	F002
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0
DSP Module	1087 / 2133 / 3024 / 4022	1087 / 2133 / 3024 / 4022

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.011.008r	
JDMapCreator	1.8 and after	

What's New in Version 5.011.008r

- Added Time Alignment Error in 5G NR Signal Analyzer
 - Carrier Scanner
 - Constellation
 - Power vs Time (Frame)

- Added EVM in 5G NR Signal Analyzer
 - Constellation
 - Carrier Scanner

- Fixed an issue where the RF spectrum signal disappears.
- Not properly working touch function when user is using the stylus pen or touching the screen by a finger.
- System hang up happened when user is entering NR measurement mode or changing the measurement mode after the system turns up.

Known Limitations

- For beam analyzer feature, Ericsson and Huawei BCH 3GPP NR standard (Release-15) following confirmed. Samsung and Nokia BCH not confirmed.
- Not supportability Auto Select in Clock Source.

Release 5.010.031r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.010.031r		
	F001	F002	
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0	
DSP Module	1087 / 2133 / 3024 / 4022	1087 / 2133 / 3024 / 4022	

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.010.031r	
JDMapCreator	1.8	

What's New in Version 5.010.031r

Added 5G NR Signal Analyzer

- o Trigger Spectrum
- o Channel Power
- Occupied Bandwidth
- Spectrum Emission Mask
- ACLR
- Multi-ACLR
- Spurious Emissions
- o Beam Analyzer
- Carrier Scanner
- o Route Map
- Constellation
- Power vs Time (Symbol)
- Power vs Time (Frame)
- Enhanced Real-time Spectrum Analyzer
 - Support narrow span from 20MHz to 100MHz (1MHz Step)

Set the attenuation to 0 dB when the pre-amp is on.

Known Limitations

None

Release 5.003.007r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.003.007r		
	F001	F002	
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0	
DSP Module	1086 / 2127 / 3020	1086 / 2127 / 3020	

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.003.007r	
JDMapCreator	1.8	

What's New in Version 5.003.007r

None

Fixed Problems

- Fixed the global 30 days license issue
- Fixed the frequency, amplitude and spur issue when the language is set to other than English
- Fixed the frequency locking issue in Beam Analyzer
- Fixed the SCPI RF Control command issue

Known Limitations

■ The real time spectrum logging has time constraints, Internal memory is up to 4 GBytes and has limiting spectrum logging for maximum 48~50 min or so. For long time logging, use of external memory is recommended.

Release 5.002.007r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.002.007r		
	F001	F002	
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0	
DSP Module	1086 / 2127 / 3020	1086 / 2127 / 3020	

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.002.007r	
JDMapCreator	1.7	

What's New in Version 5.002.007r

- 5GTF:
 - Added BRS TX Period 20 ms and Auto
 - o Added Ant and Sym parameters in Beam Index information in Beam Analyzer
 - Route Map:
 - Added a feature for pausing when logging
 - Changed the color map by supporting 15 different color levels
 - Added to indicate the currently measuring PCI

Fixed Problems

- The default for Plot Point menu is changed to GPS in Route Map mode.
- Fixed an error that DNC Preamp menu is not showing in 5GTF mode.
- The information tab is also saved when saving the result file in 5GTF Route Map mode.

Known Limitations

■ The real time spectrum logging has time constraints, Internal memory is up to 4 GBytes and has limiting spectrum logging for maximum 48~50 min or so. For long time logging, use of external memory is recommended.

Release 5.001.022r

Version Numbers

The following table lists the versions of related VIAVI hardware and/or software that can be used in conjunction with this release for CA5000 CellAdvisor 5G.

Hardware Configuration

VIAVI Hardware	Version(s) Compatible with this Release 5.001.022r		
	F001	F002	
RF Module	1.0 / 1.0 / 4.0	1.0 / 1.0 / 1.0	
DSP Module	1086 / 2127 / 3018	1086 / 2127 / 3018	

Recommended Application Software

VIAVI Software	Version(s) Compatible with this Release 5.001.022r	
JDMapCreator	1.7	

What's New in Version 5.001.022r

- Full flexibility to test multi-radio access technologies from 3G to 5G for macro-cell and smallcell site, DAS, and C-RAN.
- Small cell signal modulation quality assessment in 24 GHz and 40 GHz bands with channels up to 100 MHz.
- Real-time spectrum with persistence for effective interference analysis.
 - o 50 MHz bandwidth Real-time spectrum analyzer
 - o 100 MHz bandwidth Real-time spectrum analyzer
- Interference analyzer.
- Route map.
- Gated sweep.
- 5G TF Beamforming Analyzer.
- Scanner.
- RF Power Meter.
- GPS connectivity.
- Bluetooth connectivity.
- Wi-Fi connectivity.

Fixed Problems

None

Known Limitations

■ The real time spectrum logging has time constraints, Internal memory is up to 4 GBytes and has limiting spectrum logging for maximum 48~50 min or so. For long time logging, use of external memory is recommended.

Technical Assistance

For assistance related to the use of your product, call or e-mail VIAVI Technical Assistance Center (TAC) in your region. For a current listing of TAC phone numbers and e-mail addresses, go to: http://www.viavisolutions.com/en/services-and-support/support/technical-assistance

Document History

Revision	Date	Reason for revision
----------	------	---------------------

22125691 rev 001 June 10, 2018 5.001.027r Firmware Release 22125691 rev 002 July 12, 2018 5.001.022r Firmware Release 22125691 rev 003 Aug 09, 2018 5.002.007r Firmware Release 22125691 rev 004 Sep 17, 2018 5.003.007r Firmware Release 22125691 rev 005 Nov 30, 2018 5.010.031r Firmware Release 22125691 rev 006 Dec 06, 2018 5.011.008r Firmware Release 22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 011 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release			
22125691 rev 003 Aug 09, 2018 5.002.007r Firmware Release 22125691 rev 004 Sep 17, 2018 5.003.007r Firmware Release 22125691 rev 005 Nov 30, 2018 5.010.031r Firmware Release 22125691 rev 006 Dec 06, 2018 5.011.008r Firmware Release 22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 010 June 05, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.050.022r Firmware Release 22125691 rev 014 Nov 06, 2019 5.055.021r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.025r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 21, 2020 5.060.06r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release	22125691 rev 001	June 10, 2018	5.001.007r Firmware Release
22125691 rev 004 Sep 17, 2018 5.003.007r Firmware Release 22125691 rev 005 Nov 30, 2018 5.010.031r Firmware Release 22125691 rev 006 Dec 06, 2018 5.011.008r Firmware Release 22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 010 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 011 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.045.032r Firmware Release 22125691 rev 013 Oct 08, 2019 5.055.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.025r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.00fr Firmware Release 22125691 rev 018 May 21, 2020 5.066.00fr Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.00fr Firmware Release	22125691 rev 002	July 12, 2018	5.001.022r Firmware Release
22125691 rev 005 Nov 30, 2018 5.010.031r Firmware Release 22125691 rev 006 Dec 06, 2018 5.011.008r Firmware Release 22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 011 Aug 27, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.055.021r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.021r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 021 Nov 18, 2020 5.076.002r Firmware Release 22125691 rev 021 Nov 18, 2020 5.076.002r Firmware Release 22125691 rev 021 Nov 18, 2020 5.080.032r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.080.000r Firmware Release 22125691 rev 025 July 21, 2021 5.080.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.115.011r Firmware Release	22125691 rev 003	Aug 09, 2018	5.002.007r Firmware Release
22125691 rev 006 Dec 06, 2018 5.011.008r Firmware Release 22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 022 Mar 12, 2021 5.086.001r Firmware Release	22125691 rev 004	Sep 17, 2018	5.003.007r Firmware Release
22125691 rev 007 Mar 21, 2019 5.020.029r Firmware Release 22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.050.022r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.066.001r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.002r Firmware Release 22125691 rev 022 Mar 12, 2021 5.080.032r Firmware Release	22125691 rev 005	Nov 30, 2018	5.010.031r Firmware Release
22125691 rev 008 Mar 29, 2019 5.021.003r Firmware Release 22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.065.041r Firmware Release 22125691 rev 029 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 020 Jul 30, 2020 5.070.021r Firmware Release 22125691 rev 021 Nov 18, 2020 5.076.002r Firmware Release 22125691 rev 022 Mar 12, 2021 5.080.032r Firmware Release 22125691 rev 023 May 21, 2021 5.080.00r Firmware Release	22125691 rev 006	Dec 06, 2018	5.011.008r Firmware Release
22125691 rev 009 April 26, 2019 5.022.009r Firmware Release 22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.080.032r Firmware Release 22125691 rev 023 May 12, 2021 5.080.0032r Firmware Release 22125691 rev 024 May 21, 2021 5.080.000r Firmware Release	22125691 rev 007	Mar 21, 2019	5.020.029r Firmware Release
22125691 rev 010 June 05, 2019 5.030.049r Firmware Release 22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 021 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.080.002r Firmware Release 22125691 rev 025 Jully 21, 2021 5.086.000r Firmware Release	22125691 rev 008	Mar 29, 2019	5.021.003r Firmware Release
22125691 rev 011 Aug 21, 2019 5.040.028r Firmware Release 22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 021 Nov 18, 2020 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.086.000r Firmware Release 22125691 rev 025 July 21, 2021 5.096.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.095.035r Firmware Release <	22125691 rev 009	April 26, 2019	5.022.009r Firmware Release
22125691 rev 012 Aug 27, 2019 5.041.028r Firmware Release 22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.080.032r Firmware Release 22125691 rev 023 May 21, 2021 5.080.002r Firmware Release 22125691 rev 024 May 21, 2021 5.080.000r Firmware Release 22125691 rev 025 July 21, 2021 5.080.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release	22125691 rev 010	June 05, 2019	5.030.049r Firmware Release
22125691 rev 013 Oct 08, 2019 5.045.032r Firmware Release 22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.080.032r Firmware Release 22125691 rev 023 May 21, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release	22125691 rev 011	Aug 21, 2019	5.040.028r Firmware Release
22125691 rev 014 Nov 06, 2019 5.050.022r Firmware Release 22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.095.035r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release	22125691 rev 012	Aug 27, 2019	5.041.028r Firmware Release
22125691 rev 015 Dec 17, 2019 5.055.021r Firmware Release 22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 030 Dec 16, 2022 5.105.016r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.014r Firmware Release	22125691 rev 013	Oct 08, 2019	5.045.032r Firmware Release
22125691 rev 016 Dec 26, 2019 5.055.025r Firmware Release 22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.095.035r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 014	Nov 06, 2019	5.050.022r Firmware Release
22125691 rev 017 May 07, 2020 5.060.067r Firmware Release 22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 015	Dec 17, 2019	5.055.021r Firmware Release
22125691 rev 018 May 21, 2020 5.061.002r Firmware Release 22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 016	Dec 26, 2019	5.055.025r Firmware Release
22125691 rev 019 Jul 23, 2020 5.065.041r Firmware Release 22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 017	May 07, 2020	5.060.067r Firmware Release
22125691 rev 020 Jul 30, 2020 5.066.001r Firmware Release 22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 018	May 21, 2020	5.061.002r Firmware Release
22125691 rev 021 Nov 18, 2020 5.070.021r Firmware Release 22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 019	Jul 23, 2020	5.065.041r Firmware Release
22125691 rev 022 Mar 12, 2021 5.076.002r Firmware Release 22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 020	Jul 30, 2020	5.066.001r Firmware Release
22125691 rev 023 May 12, 2021 5.080.032r Firmware Release 22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 021	Nov 18, 2020	5.070.021r Firmware Release
22125691 rev 024 May 21, 2021 5.081.000r Firmware Release 22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 022	Mar 12, 2021	5.076.002r Firmware Release
22125691 rev 025 July 21, 2021 5.086.000r Firmware Release 22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 023	May 12, 2021	5.080.032r Firmware Release
22125691 rev 026 Aug 18, 2021 5.090.018r Firmware Release 22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 024	May 21, 2021	5.081.000r Firmware Release
22125691 rev 027 Dec 23, 2021 5.095.035r Firmware Release 22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 025	July 21, 2021	5.086.000r Firmware Release
22125691 rev 028 April 29, 2022 5.100.029r Firmware Release 22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 026	Aug 18, 2021	5.090.018r Firmware Release
22125691 rev 029 Aug 26, 2022 5.105.016r Firmware Release 22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 027	Dec 23, 2021	5.095.035r Firmware Release
22125691 rev 030 Dec 16, 2022 5.110.014r Firmware Release 22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 028	April 29, 2022	5.100.029r Firmware Release
22125691 rev 031 Jan 06, 2023 5.110.015r Firmware Release 22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 029	Aug 26, 2022	5.105.016r Firmware Release
22125691 rev 032 Apr 28, 2023 5.115.011r Firmware Release	22125691 rev 030	Dec 16, 2022	5.110.014r Firmware Release
	22125691 rev 031	Jan 06, 2023	5.110.015r Firmware Release
	22125691 rev 032	Apr 28, 2023	5.115.011r Firmware Release
22125691 rev 033 Aug 23, 2023 5.120.003r Firmware Release	22125691 rev 033	Aug 23, 2023	5.120.003r Firmware Release
22125691 rev 034 Dec 19, 2023 5.125.015r Firmware Release	22125691 rev 034	Dec 19, 2023	5.125.015r Firmware Release
22125691 rev 035 May 20, 2024 5.130.003r Firmware Release	22125691 rev 035	May 20, 2024	5.130.003r Firmware Release

